

Laundry Tubs

Faucet Cross Connection Hazard




Unprotected Cross Connection



Faucets with hose threads that allow connection of a hose must be protected with a hose bib vacuum breaker (HBVB)



Direct Cross Connection




HBVB

Protected Hose Connection with HBVB



Sink overflow edge



Strainer bottom

Unprotected Faucets (with hose threads allowing connection of garden hose) require installation of a hose bib vacuum breaker (HBVB).

Faucets without hose threads do NOT require installation of a hose bib vacuum breaker provided the the bottom of the faucet strainer is not less than 1-inch above sink overflow edge.

No potential cross connection hazard if 1-inch height requirement is met above sink overflow edge.